

Название агрегата	Номин. подача, м ³ /ч	Номин. напор, м	Рабочая зона		Кавит. запас, м	Электродвигатель	
			подача, м ³ /ч	напор, м		кВт	об/мин
ЦНС 2,5-80	2,5	80	1...3	70...89	3,0	2,2	3000
ЦНС 2,5-120	2,5	120	1...3	105...133	3,0	3	3000
ЦНС 2,5-160	2,5	160	1...3	140...177	3,0	4	3000
<u>ЦНС 13-70</u>	13	70	11...15	69...71	3,0	11	3000
<u>ЦНС 13-105</u>	13	105	11...15	100...106	3,0	11	3000
<u>ЦНС 13-140</u>	13	140	11...15	137...141	3,0	15	3000
<u>ЦНС 13-175</u>	13	175	11...15	168...179	3,0	18,5	3000
<u>ЦНС 13-210</u>	13	210	11...15	200...215	3,0	18,5	3000
<u>ЦНС 13-245</u>	13	245	11...15	235...250	3,0	22	3000
<u>ЦНС13-280</u>	13	280	11...15	268...285	3,0	30	3000
<u>ЦНС 13-315</u>	13	315	11...15	300...320	3,0	30	3000
<u>ЦНС 13-350</u>	13	350	11...15	338...358	3,0	30	3000
<u>ЦНС 38-44</u>	38	44	28...48	30...52	3,6	11	3000
<u>ЦНС 38-66</u>	38	66	28...48	50...77	3,6	15	3000
<u>ЦНС 38-88</u>	38	88	28...48	67...102	3,6	18,5	3000
<u>ЦНС 38-110</u>	38	110	28...48	83...127	3,6	22	3000
<u>ЦНС 38-132</u>	38	132	28...48	100...153	3,6	30	3000
<u>ЦНС 38-154</u>	38	154	28...48	117...179	3,6	30	3000
<u>ЦНС 38-176</u>	38	176	28...48	135...200	3,6	30	3000
<u>ЦНС 38-198</u>	38	198	28...48	150...228	3,6	37	3000

<u>ЦНС 38-220</u>	38	220	28...48	170...252	3,6	45	3000
<u>ЦНС 60-66</u>	60	66	48...80	50...72	4,5	22	3000
<u>ЦНС 60-99</u>	60	99	48...80	73...108	4,5	30	3000
<u>ЦНС 60-132</u>	60	132	48...80	100...145	4,5	45	3000
<u>ЦНС 60-165</u>	60	165	48...80	123...180	4,5	55	3000
<u>ЦНС 60-198</u>	60	198	48...80	150...215	4,5	55	3000
<u>ЦНС 60-231</u>	60	231	48...80	175...252	4,5	75	3000
<u>ЦНС 60-264</u>	60	264	48...80	190...287	4,5	75	3000
<u>ЦНС 60-297</u>	60	297	48...80	225...325	4,5	75	3000
<u>ЦНС 60-330</u>	60	330	48...80	250...360	4,5	90	3000
	60	330	48...80	250...360	4,5	110	3000
ЦНС 105-98	105	98	80...130	85...105	5,5	55	3000
ЦНС 105-147	105	147	80...130	122...160	5,5	75	3000
ЦНС 105-196	105	196	80...130	160...215	5,5	110	3000
ЦНС 105-245	105	245	80...130	200...270	5,5	132	3000
ЦНС 105-294	105	294	80...130	245...328	5,5	160	3000
ЦНС 105-343	105	343	80...130	285...385	5,5	160	3000
ЦНС 105-392	105	392	80...130	325...435	5,5	200	3000
ЦНС 105-441	105	441	80...130	370...490	5,5	250	3000
ЦНС 105-490	105	490	80...130	410...540	5,5	250	3000
ЦНС 180-85	180	85	130...220	70...90	4,0	75	1500
ЦНС 180-128	180	128	130...220	105...140	4,0	110	1500

ЦНС 180-170	180	170	130...220	135...185	4,0	132	1500
ЦНС 180-212	180	212	130...220	175...235	4,0	160	1500
ЦНС 180-255	180	255	130...220	210...280	4,0	200	1500
ЦНС 180-297	180	297	130...220	245...330	4,0	250	1500
ЦНС 180-340	180	340	130...220	280...375	4,0	250	1500
ЦНС 180-383	180	383	130...220	315...420	4,0	315	1500
ЦНС 180-425	180	425	130...220	350...470	4,0	315	1500
ЦНС 300-120	300	120	220...360	110...135	4,5	160	1500
ЦНС 300-180	300	180	220...360	162...200	4,5	250	1500
ЦНС 300-240	300	240	220...360	215...262	4,5	315	1500
ЦНС 300-300	300	300	220...360	265...325	4,5	400	1500
ЦНС 300-360	300	360	220...360	325...390	4,5	500	1500
ЦНС 300-420	300	420	220...360	375...455	4,5	500	1500
ЦНС 300-480	300	480	220...360	430...520	4,5	630	1500
ЦНС 300-540	300	540	220...360	485...585	4,5	800	1500
ЦНС 300-600	300	600	220...360	538...650	4,5	800	1500